

## **TJI® Joists with Flak Jacket® Protection Scope of Work for Mechanical Removal of Flak Jacket Coating Updates and Clarifications dated October 23, 2017**

Weyerhaeuser is issuing the following updates and clarifications on the TJI® Joists with Flak Jacket® Protection Scope of Work for Mechanical Removal of Flak Jacket Coating:

### **Alternative to 95% Removal Requirement**

To provide additional flexibility for homes that are being remediated by mechanical removal of Flak Jacket coating, the standard regarding “removal of at least 95% of the visible web surface area on all Gen 4 joists and blocking panels” and subsequent application of 10 wet mils of the top coat paint may be modified on any affected home as follows:

- Removal of approximately **85% of the visible web surface area** on all Gen 4 joists and blocking panels, to the extent it is followed by
- Coverage of at least **18 wet mils** of the top coat paint.